



## WIRING DIAGRAM

HIGH SPEED SIGNAL			
P1,P2(4x-Pluggable-QSFP)			
PAD	SIGNAL	PAD	SIGNAL
01	GND	20	GND
02	TX2n	21	RX2n
03	TX2p	22	RX2p
04	GND	23	GND
05	TX4n	24	RX4n
06	TX4p	25	RX4p
07	GND	26	GND
08	ModSelL	27	ModPrsL
09	ResetL	28	IntL
10	VccRx	29	VccTx
11	SCL	30	Vcc1
12	SDA	31	LPMode
13	GND	32	GND
14	RX3p	33	TX3p
15	RX3n	34	TX3n
16	GND	35	GND
17	RX1p	36	TX1p
18	RX1n	37	TX1n
19	GND	38	GND



△					Date	2013.01.14	Part No.	See Table	 <b>ACE PLUS CORP.</b>				
△					Design					Customer			
△					Check					P/N			
Revision	Data	Content	Confirm	Design	Confirm				DWG.No.		Version	1.0	